# HP 905 & 955 ALERT

⚠️ 📶 ⚠️

On the 9th of April, the factory found both HP 905 & HP 955 series printers are prompting for a upgrade. The message shown is "WIFI detects a new firmware version." **DO NOT RUN THE UPGRADE !**

Update the Printer	Cartridge Problem
Check for Printer Updates Now >	Remove and reinstall the indicated cartridge, making sure it is correctly installed.
Printer Update Options Do Not Check >	If this message continues to appear, replace the indicated cartridge.

If you update the driver ➡️ Your installed Cartridges will not work anymore

## How to proceed ?
Please click ' NO" to refuse the update.

How to turn off automatic firmware detection

1: On the printer control panel, swipe down to open the Dashboard and select the Setup Icon

2: Select Printer Maintenance from the menu list.

Setup
- Cartridge Information >
- Printer Maintenance >
- Power Management >

Printer Maintenance
- Clean Printhead >
- Align Printhead >
- Update the Printer >

3: Select Update the printer from the menu list.

Update the Printer
- Check for Printer Updates Now >
- Printer Update Options Do Not Check >

4: Select Printer update options from the menu list

Printer Update Options
- ○ Install Automatically (Recommended) >
- ○ Alert When Available >
- ● Do Not Check >

5: Select Do Not check from the list.

Update Available
An update is available that can improve the printer's performance. Would you like to install the update?

No | Yes

6: Select No to cancel the update.